

Previous Dante Accelerator Driver **for Mac version information**

V2.5.2

Specification Changes

- Changed the system requirements to the following.
OS X 10.9.5, OS X 10.10.5, OS X 10.11.x, macOS 10.12.x, macOS 10.13.x, macOS 10.14*
*(Cannot be installed on macOS 10.14.4 or later.)

Known Issue

- Dante Accelerator Driver may not work if the Thunderbolt Expansion Box is connected to a Mac computer after starting the Mac. Make sure to connect the Thunderbolt Expansion Box to the computer before starting it.

V2.5.1

Specification Changes

- Now supports Nuendo 6.5.

Known Issue

- Dante Accelerator Driver may not work if the Thunderbolt Expansion Box is connected to a Mac computer after starting the Mac. Make sure to connect the Thunderbolt Expansion Box to the computer before starting it.

V2.5.0

Specification Changes

- Mac Pro (Late 2013) is now supported. You will need the Thunderbolt Expansion Box to connect Dante Accelerator to the Thunderbolt port of a Mac computer. Following models to be verified for use with Dante Accelerator.

- Sonnet Echo Express SE II / Echo Express III-D/ Echo Express/ Echo Express Pro
- Magma ExpressBox 1T/3T (non-Thunderbolt 2 compliant model)

Known Issue

- Dante Accelerator Driver may not work if the Thunderbolt Expansion Box is connected to a Mac computer after starting the Mac. Make sure to connect the Thunderbolt Expansion Box to the computer before starting it.

V2.0.0

Specification Changes

- Now supports Dante Redundancy. (The secondary port became available.)
- Changed the system requirements to the following. OS X 10.7.5 or 10.8.x.

Fixed Bug

- Solved the problem in which the Dante Accelerator for which Pull up/Pull down is set to enable does not work properly in OS X 10.8.

Known Issue

- None.

V1.0.1

Specification Changes

- Disabled the Pull up/Pull down settings in OS X 10.8 which does not support Pull up/Pull down.
- This driver does not support Dante Accelerator Firmware V1.0.0. Dante Accelerator Firmware V1.0.1 or later is required for use.

Fixed Bug

- Solved the problem in which the audio sound would not play back properly when two audio applications were simultaneously using Dante Accelerator.

Known Issue

- If the buffer size is set to 2048 when the audio buses in the VST Connections of Nuendo are set to less than 32 channels in OS X 10.6.8, continual noise may occur. Set the value to something other than 2048.

V1.0.0

1st. Release Version.